

Member Advisory

ISSUED: September 25, 2018

NUMBER: MA 18-08

FROM: Club Racing Board

TO: All Participants

SUBJECT: TA2 Roll Cages

It has come to the attention of the SCCA that roll cage structures in certain TA2 cars do not meet the roll cage specifications as outlined in GCR section 9.4. Regardless if the car has a current logbook, any car not meeting the outer diameter and tubing wall thicknesses will not be allowed to compete in SCCA sanctioned events. Contact a nationally licensed SCCA scrutineer if you need verification of compliance.