

RACING MEMO

ISSUED: June 27, 2019

NUMBER: RM 19-05

FROM: Board of Directors

TO: All Participants

SUBJECT: GT1 Mustang Bodywork Error and Omission in July Fastrack

In GCR section 9.1.2.E.c. add the following:

"* ACP (2010) MUSTANG bodywork only may add 2.0" to the front splitter length. Roof height 46.5" min. (measured from the ground). Air may be ducted to the carburetor airbox through an opening in the back of the hood, rectangular in shape, maximum width of 20", maximum length 3.5". Opening may extend 1" into the windshield. *Mustang Five Star (2018) TA2 body allowed.*"

SPORTS CAR CLUB OF AMERICA, INC

PO Box 19400, Topeka, KS 66619-0400

(800) 770-2055 Fax (785) 232-7214 www.scca.com